

Inspection Report Summary

Department:	Instafoil
Machine:	C & P
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	10 minutes
Auditor:	Hussein Saleh
Inspected Date:	Jan 6, 2026

Inspection Report

Facility: EHS Demo


Department: Instafoil

Machine: C & P

Model Number:

Manufacturer:

Serial Number:



Machine Specific


Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Load Material	Crush-hand in working area		Pass	2	2	2	PR18	None	Front Shield
Load Material	Entangled - contact with power transmission		Pass	2	2	2	PR18	Awareness Shield	Enclose Wheel

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Department Specific

#	Question	Corrective Action	Pass/Fail
1.	Are Emergency Exits clear and unobstructed?		Fail
2.	Are Emergency Exits clearly identified?		Fail
3.	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		Fail
4.	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		Fail
5.	Are the Eyewash Stations working and clean, and unobstructed?		Fail
6.	Are all the sprinkler heads in your location unobstructed?		Fail
7.	Is Access to the Electrical Panels clear and unobstructed?		Fail
8.	Are carts in good condition?		Fail
9.	Is the lighting all functioning properly and adequate for the area?		Fail
10.	Are noise levels adequate with PPE, any high impulse or continual noise?		Fail
11.	Is the temperature in the area comfortable to work in?		Fail
12.	Are all air quality systems working (dust, fumes or vapour present)?		Fail
13.	Is the housekeeping (floor and work surfaces) sufficient for the area?		Fail
14.	Are the employees using their PPE?		Fail
15.	Are all controlled substances labelled in accordance with GHS standards?		Fail

Safety Rep Signature:



Supervisor Signature:

