

Inspection Report Summary

Department:	Graphics Lab
Machine:	Bambu 3D Printer
Pass / Fail:	50 % Passed / 50 % Failed
Time to Audit:	4 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 13, 2026

Inspection Report

Facility: Acadia Junior High

Department: Graphics Lab

Machine: Bambu 3D Printer

Model Number:

Manufacturer: Bambu Lab

Serial Number:




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Print part	Burn, entanglement , crush		Pass	1	2	2	PR2 4	Full enclosure	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?	2026 Inspection - Create safe work procedure for printers	Fail
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature:

A rectangular box containing a handwritten signature. The signature consists of the letters 'K' and 'E' written in a cursive, stylized manner. The 'K' is on the left and the 'E' is on the right, with a vertical line extending from the top of the 'E'.