

Inspection Report Summary

Department:	Graphics Lab
Machine:	Ultimaker2+ 3D printer
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	0 minutes
Auditor:	Kristin Petaski
Inspected Date:	May 13, 2026

Inspection Report

Facility: Acadia Junior High

Department: Graphics Lab

Machine: Ultimaker2+ 3D printer

Model Number:

Manufacturer: Ultimaker

Serial Number:



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Print part	Burn, entanglement , crush		Pass	1	2	2	PR2 4	2025 Audit - Full enclosure	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		N/A
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature:

A rectangular box containing a handwritten signature in black ink. The signature is stylized, starting with a vertical line, followed by a loop, and ending with a horizontal stroke.