

Inspection Report Summary

Department:	Woodworking
Machine:	General International Jointer
Pass / Fail:	75 % Passed / 25 % Failed
Time to Audit:	3 minutes
Auditor:	Kristin Petaski
Inspected Date:	May 13, 2026

Inspection Report

Facility: Vincent Massey Collegiate

Department: Woodworking

Machine: General International Jointer

Model Number:

Manufacturer: General International

Serial Number: PTSD15-000228



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Operate machine	Laceration, amputation from blade	2026 Inspection- Repair or replace spring on blade guard. It is getting stuck and difficult to move. 	Fail	2	2	2	PR1 8	Hinged guard	
Operate machine	Entangle, crush in power transmission		Pass	2	2	2	PR1 8	Fixed guard	
Third party access	Laceration, amputation from tooling		Pass	2	2	2	PR1 8	Hinged guard, hazard markings on floor	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature:

A handwritten signature in black ink, consisting of a large, stylized 'P' with a vertical line through it, enclosed within a rectangular box.