Inspection Report Summary

Department:	Woodworking
Machine:	Rikon Belt and Disc Sander
Pass / Fail:	75 % Passed / 25 % Failed
Time to Audit:	0 minutes
Auditor:	Kristin Petaski
Inspected Date:	May 13, 2026

Inspection Report

Facility: Vincent Massey Collegiate

Department: Woodworking

Machine: Rikon Belt and Disc Sander

Model Number: 50-144 (120V, 5.8 A, 5/8 hp)

Manufacturer: Rikon

Serial Number: PTSD15-000201



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Sand part on disc	Abrasion or entangle		Pass	2	1	2	PR2 4	Half disc guard	
Sand part on belt	Abrasion or entangle		Pass	2	1	2	PR2 4	Swp	
Maintenance	Entangle in pulleys		Pass	2	1	2	PR2 4	Belt and pulley guard	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Fail
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature: