

Inspection Report Summary

Department:	Woodworking
Machine:	Laguna Horizontal Belt Sander
Pass / Fail:	75 % Passed / 25 % Failed
Time to Audit:	1 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 13, 2026

Inspection Report

Facility: Vincent Massey Collegiate

Department: Woodworking

Machine: Laguna Horizontal Belt Sander

Model Number: 689T

Manufacturer: Laguna

Serial Number:



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Sand Part	Entangle, abrasion		Pass	2	2	2	PR1 8	Awareness shield over belt and end pulley	
Operate Machine	Entanglement, Contact with power transmission		Pass	2	1	1	PR4 2	Secure power transmission guard	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Fail
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A handwritten signature in black ink, consisting of a stylized 'M' or 'W' shape with a vertical line to the left and a horizontal line above the main structure.