

Inspection Report Summary

Department:	Woodworking
Machine:	General International Band Saw
Pass / Fail:	80 % Passed / 20 % Failed
Time to Audit:	3 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 20, 2026

Inspection Report

Facility: Westdale School

Department: Woodworking

Machine: General International Band Saw

Model Number: 90-140 M1 (120V, 10A, 60HZ, 1PH, 1HP)

Manufacturer: General International

Serial Number: PTSD-000302




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Cut part	Amputation from blade	2026 Inspection - Replace blade guard to cover exposed side of blade 	Fail	2	2	2	PR1 8	Adjustable blade guard	
Third party access	Laceration, amputation from blade		Pass	2	2	2	PR1 8	Blade guard, located against wall, hazard markings on floor	
Operate machine	Crush, entangle in power transmission		Pass	2	2	2	PR1 8	Hinged guards - secured with bolts	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A rectangular box containing a handwritten signature in black ink. The signature appears to be 'JEL' or 'JEL' with a stylized flourish.