

Inspection Report Summary

Department:	Woodworking
Machine:	Modela CNC Mill
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	0 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 20, 2026

Inspection Report

Facility: Ecole Charleswood Junior High

Department: Woodworking

Machine: Modela CNC Mill

Model Number: MDX-50

Manufacturer: DGShape

Serial Number:



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Operate machine	Laceration, crush, entangle		N/A	2	2	2	PR18	Interlocked enclosure guard	Safety- rated interlocked enclosure

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

IEI