

Inspection Report Summary

Department:	Wood Shop
Machine:	Rikon Belt and Disc Sander
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	1 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 26, 2026

Inspection Report

Facility: Facility Maintenance

Department: Wood Shop

Machine: Rikon Belt and Disc Sander

Model Number: 50-120 (120V, 60HZ, 3/4HP)

Manufacturer: Rikon

Serial Number: PTSD15-006



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Sand part on belt	Abrasion, entangle		Pass	2	2	2	PR1 8	Adjustable guard	
Third party access	Abrasion, entangle		Pass	2	2	2	PR1 8	Adjustable guard, hazard markings on floor	
Sand part on disc	Abrasion, entangle		Pass	2	2	2	PR1 8	Adjustable Shield	
Operate machine	Entangle in pulley, abrasion from belt			2	2	2	PR1 8	Pulley and rear guard	
Operate machine	Entangle, crush in power transmission		Pass	2	2	2	PR1 8	Fixed guard	
Sand part on belt	Struck by part		Pass	2	1	2	PR2 4	Part rest on belt	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

IEI