

Inspection Report Summary

Department:	Wood Shop
Machine:	Laguna Horizontal Belt Sander
Pass / Fail:	75 % Passed / 25 % Failed
Time to Audit:	1 minutes
Auditor:	Idongesit Inwang
Inspected Date:	May 27, 2026

Inspection Report

Facility: Bison Run School

Department: Wood Shop

Machine: Laguna Horizontal Belt Sander


Model Number: 689T (1.5 HP, 110V, 18A, 60H)

Manufacturer: Laguna

Serial Number: 2208058



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Sand part	Entangle, abrasion	2026 Inspection - Fix shield in place 	Fail	2	2	2	PR1 8	Awareness shield over belt and end pulley	
Operate machine	Crush in power transmission		Pass	2	2	2	PR1 8	Secure power transmission guards	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A handwritten signature in black ink, consisting of a stylized 'A' followed by a vertical line and a horizontal line, enclosed in a rectangular box.