

# Inspection Report Summary

|                 |                           |
|-----------------|---------------------------|
| Department:     | Library                   |
| Machine:        | Ultimaker 3D Printer      |
| Pass / Fail:    | 50 % Passed / 50 % Failed |
| Time to Audit:  | 0 minutes                 |
| Auditor:        | Idongesit Inwang          |
| Inspected Date: | May 27, 2026              |

# Inspection Report

**Facility:** South Pointe School

**Department:** Library

**Machine:** Ultimaker 3D Printer

**Model Number:** U

**Manufacturer:** Ultimaker

**Serial Number:**



## Machine Specific

| Activity/Tasks | Hazards     | Corrective Action | Pass/Fail | Severity | Exposure | Avoidance | Total    | Current Safeguards    | Recommended Improvements |
|----------------|-------------|-------------------|-----------|----------|----------|-----------|----------|-----------------------|--------------------------|
| Print part     | Crush, burn |                   | Pass      | 1        | 2        | 1         | PR3<br>2 | Fixed enclosure guard |                          |

| #  | Question                                                         | Corrective Action | Pass/Fail |
|----|------------------------------------------------------------------|-------------------|-----------|
| 1. | Safe Work Procedure posted?                                      |                   | Fail      |
| 2. | Are all Emergency Stops clearly marked and functioning properly? |                   | N/A       |

**Safety Rep Signature:**

A handwritten signature in black ink, consisting of a stylized 'L' followed by a 'D' with a horizontal bar, enclosed in a rectangular box.