

Inspection Report Summary

Department:	Wood Shop
Machine:	Delta Mortiser
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	0 minutes
Auditor:	Kristin Petaski
Inspected Date:	Jun 9, 2026

Inspection Report

Facility: Grant Park High School

Department: Wood Shop

Machine: Delta Mortiser

Model Number:

Manufacturer: Delta Milwaukee

Serial Number: 699-50-shop equip-001



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Operate machine	Entangle in power transmission		Pass	2	2	2	PR1 8	Fixed guards	
Operate machine	Entangle, laceration		Pass	2	2	2	PR1 8	Awareness shield around spindle	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A rectangular box containing a handwritten signature in black ink. The signature is stylized, starting with a large loop on the left and ending with a horizontal stroke on the right.