

Inspection Report Summary

Department:	Metal Shop
Machine:	Atlas Grinder
Pass / Fail:	80 % Passed / 20 % Failed
Time to Audit:	1 minutes
Auditor:	Kristin Petaski
Inspected Date:	Jun 9, 2026

Inspection Report

Facility: Grant Park High School

Department: Metal Shop

Machine: Atlas Grinder

Model Number: 24\" x 24\" - 115 V, 60/50 Hz, 1 Ph, 4.6 A

Manufacturer: Atlas

Serial Number: 699-43-shop equip-003



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Grind part	Struck by debris, abrasion		Pass	2	2	2	PR1 8	Awareness shields over discs	
Operate machine	Entangle in power transmission		Pass	2	2	2	PR1 8	Fixed guards	
Grind part	Struck by shattered disc		Pass	3	2	2	PR1 12	Shatter guards	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?	2026 Inspection - Post swp	Fail
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A handwritten signature in black ink, consisting of a large, stylized loop followed by a vertical stroke and a small horizontal tick at the bottom.