

Inspection Report Summary

Department:	Metal Shop
Machine:	King Belt & Disc Sander
Pass / Fail:	83 % Passed / 17 % Failed
Time to Audit:	1 minutes
Auditor:	Kristin Petaski
Inspected Date:	Jun 9, 2026

Inspection Report

Facility: Grant Park High School

Department: Metal Shop

Machine: King Belt & Disc Sander

Model Number: 32" x 24" - 110/220 V, 13.5/6.7 A, 60 Hz, 1 Ph

Manufacturer: King

Serial Number:



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Sand part on disc	Abrasion		Pass	1	2	2	PR2 4	Awareness shield around disc	
Sand part on belt	Abrasion		Pass	1	2	2	PR2 4	Always used horizontal	
Operate machine	Entangle in pulleys		Pass	2	2	2	PR1 8	Rear barrier	
Operate machine	Entangle in power transmission		Pass	2	2	2	PR1 8	Fixed guard	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?	2026 Inspection- post swp	Fail
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A handwritten signature, possibly reading "JP", is written in black ink within a rectangular box.