

Inspection Report Summary

Department:	Power Mech
Machine:	Manual 20 Ton Press
Pass / Fail:	67 % Passed / 33 % Failed
Time to Audit:	1 minutes
Auditor:	Kristin Petaski
Inspected Date:	Jun 9, 2026

Inspection Report

Facility: Grant Park High School


Department: Power Mech

Machine: Manual 20 Ton Press

Model Number:

Manufacturer: Canbuilt

Serial Number: 699-42-shop equip-004



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Press part	Crush, struck by part		Pass	1	2	2	PR2 4	Curtain across front	
Third party access	Crush, struck by part		Pass	1	2	2	PR2 4	Located against wall	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?	2026 Inspection- Post swp	Fail
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature:

A handwritten signature in black ink, consisting of a stylized 'A' followed by a large loop, enclosed within a rectangular box.