

Inspection Report Summary

Department:	Electronics Lab
Machine:	Grinder
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	1 minutes
Auditor:	Idongesit Inwang
Inspected Date:	Jun 9, 2026

Inspection Report

Facility: Grant Park High School


Department: Electronics Lab

Machine: Grinder

Model Number:

Manufacturer:

Serial Number: 699-26-shop equip-004




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Grind part	Struck by debris, abrasion		Pass	2	2	2	PR18	Awareness shields over discs	
Operate machine	Entangle in power transmission		Pass	2	2	2	PR18	Fixed guards	
Grind part	Struck by shattered disc		Pass	2	2	2	PR18	Shatter guards	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		N/A
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature:

A rectangular box containing a handwritten signature in black ink. The signature appears to be the letters 'LEI' written in a stylized, cursive-like font. The 'L' is on the left, followed by an 'E' with a horizontal bar, and an 'I' on the right.