

Inspection Report Summary

Department:	Electronics
Machine:	Delta Drill Press
Pass / Fail:	60 % Passed / 40 % Failed
Time to Audit:	3 minutes
Auditor:	Idongesit Inwang
Inspected Date:	Jun 16, 2026

Inspection Report

Facility: Sisler High School


Department: Electronics

Machine: Delta Drill Press

Model Number: 11-990C

Manufacturer: Delta

Serial Number: 697-19-shop equip-005



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Drill part	Entangle, struck by debris		Pass	2	2	2	PR1 8	Awareness shield	
Operate machine	Crush in power transmission		Pass	2	2	2	PR1 8	Power Transmission Cabins - Secured	
Third party access	Entangle in spindle, struck by debris		Pass	2	2	2	PR1 8	Awareness shield, located against wall, hazard markings on floor	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?	2026 Inspection - Post safe work procedure	Fail
2.	Are all Emergency Stops clearly marked and functioning properly?	2026 Inspection - secure estop firmly to frame 	Fail

Safety Rep Signature:

A handwritten signature in black ink, consisting of a stylized 'J' or 'L' shape with a vertical line to its left, enclosed within a rectangular box.