

Inspection Report Summary

Department:	Woodworking
Machine:	Excelsior Scroll Saw
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	0 minutes
Auditor:	Idongesit Inwang
Inspected Date:	Jun 17, 2026

Inspection Report

Facility: Daniel McIntyre Collegiate


Department: Woodworking

Machine: Excelsior Scroll Saw

Model Number: XL-16

Manufacturer: Excelsior

Serial Number: 164393




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Cut part	Laceration, amputation from blade		Pass	2	2	2	PR1 8	Awareness shield	
Operate machine	Crush, entangle in power transmission		Pass	2	2	2	PR1 8	Guard	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A rectangular box containing a handwritten signature. The signature consists of the letters 'J' and 'E' written in a stylized, cursive-like font. The 'J' is on the left and the 'E' is on the right, with a horizontal line connecting them. The box is empty except for the signature.