

Inspection Report Summary

Department:	Power Mechanics
Machine:	John Bean Wheel Balancer
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	0 minutes
Auditor:	Idongesit Inwang
Inspected Date:	Jun 17, 2026

Inspection Report

Facility: Daniel McIntyre Collegiate

Department: Power Mechanics

Machine: John Bean Wheel Balancer

Model Number: Smart Calibration 5.1

Manufacturer: John Bean

Serial Number: 710-105-shop equip-002




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Operate machine	Entangle		Pass	2	2	2	PR18	Guard around tire	
Operate machine	Crush in power transmission		Pass	2	2	2	PR18	Fixed guard	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

A rectangular box containing a handwritten signature in black ink. The signature is stylized, appearing to be a combination of letters and a flourish, possibly reading "C. E." or similar.