

Inspection Report Summary

Department:	Electronics
Machine:	Rikon Belt and Disc Sander
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	0 minutes
Auditor:	Idongesit Inwang
Inspected Date:	Jun 17, 2026

Inspection Report

Facility: Daniel McIntyre Collegiate


Department: Electronics

Machine: Rikon Belt and Disc Sander

Model Number: 50-142 (110V, 1PH, 1/3HP)

Manufacturer: Rikon

Serial Number: 275



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Sand part on disc	Abrasion		Pass	1	2	2	PR2 4	Awareness shield around disc	
Sand part on belt	Abrasion		Pass	1	2	2	PR2 4	Small belt. Guards around sides.	
Operate machine	Entangle in power transmission		Pass	2	2	2	PR1 8	Replace knobs on power transmission guard	
Sand part	Struck by part		Pass	2	2	2	PR1 8	Tool rest on disc and belt	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		Pass
2.	Are all Emergency Stops clearly marked and functioning properly?		Pass

Safety Rep Signature:

1 E1