

Inspection Report Summary

Department:	Graphic Arts
Machine:	Wash Sink
Pass / Fail:	100 % Passed / 0 % Failed
Time to Audit:	0 minutes
Auditor:	Idongesit Inwang
Inspected Date:	Jun 18, 2026

Inspection Report

Facility: Sargent Park School


Department: Graphic Arts

Machine: Wash Sink

Model Number:

Manufacturer: Rhinotech

Serial Number:




Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Wash parts	Spray		Pass	1	2	2	PR2 4	Basin, PPE	
Walk around area	Laceration from sharp parts on water lines		Pass	1	2	1	PR3 2	Guard around water lines	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		N/A
2.	Are all Emergency Stops clearly marked and functioning properly?		N/A

Safety Rep Signature:

A rectangular box containing a handwritten signature in black ink. The signature consists of the letters 'L', 'E', and 'I' written in a stylized, cursive-like font. The 'L' is on the left, the 'E' is in the middle, and the 'I' is on the right. The box is empty except for the signature.