

Inspection Report Summary

Department:	Core Room
Machine:	Laempe #3201
Pass / Fail:	0 % Passed / 0 % Failed
Time to Audit:	1 minutes
Auditor:	Willi Fast
Inspected Date:	Oct 7, 2026

Inspection Report

Facility: Winkler

Department: Core Room

Machine: Laempe #3201

Model Number: N/A

Manufacturer: Laempe

Serial Number: 3201



Machine Specific

Activity/Tasks	Hazards	Corrective Action	Pass/Fail	Severity	Exposure	Avoidance	Total	Current Safeguards	Recommended Improvements
Point of Operation	Crush in actuating table			3	2	1	PR2 6	Perimeter light curtain. Plastic curtain descends during operation (opening at bottom still allows access to crush points).	Fully close all openings in plastic curtain to restrict access to all crush points or re-design light curtain to disable all motion when activated.
Third Party Protection	Crush in actuating components			3	2	1	PR2 6	Interlocked doors around rear and sides of machine	
Power Transmission	crush in power transmission components			3	2	1	PR2 6	Fixed guarding	
Other Hazards	N/A			3	2	1	PR2 6	N/A	

#	Question	Corrective Action	Pass/Fail
1.	Safe Work Procedure posted?		
2.	Are all Emergency Stops clearly marked and functioning properly?		

Department Specific

#	Question	Corrective Action	Pass/Fail
1.	Are Emergency Exits clear and unobstructed?		
2.	Are Emergency Exits clearly identified?		
3.	Are Fire Extinguishers/Fire Control Equipment clearly visible and identified?		
4.	Have the Fire Extinguishers/Fire Control Equipment been recently inspected?		
5.	Are the Eyewash Stations working and clean, and unobstructed?		
6.	Are all the sprinkler heads in your location unobstructed?		
7.	Is Access to the Electrical Panels clear and unobstructed?		
8.	Are carts in good condition?		
9.	Is the lighting all functioning properly and adequate for the area?		
10.	Are noise levels adequate with PPE, any high impulse or continual noise?		
11.	Is the temperature in the area comfortable to work in?		
12.	Are all air quality systems working (dust, fumes or vapour present)?		
13.	Is the housekeeping (floor and work surfaces) sufficient for the area?		
14.	Are the employees using their PPE?		
15.	Are all controlled substances labelled in accordance with GHS standards?		

Signatures (capture on paper after printing): _____